

Menu

HISTORY FILE MAP for year 2003

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

231.16:22-16:28 6m realtime 1024bps data lost due to long 1-way to 2-way acquisition at DSS24. No DR was raised.
Subreflector problems at DSS24 led to multiple data outages. DR G103227 refers. Outage summary as follows:
231.17:04-17:22 18m realtime 1024 bps data lost.
231.17:49-17:58 9m realtime 1024 bps data lost.
231.18:14-18:25 84% realtime 1024 and 512bps data lost.

